

GOVERNMENT OF TELANGANA
ABSTRACT

Minor Irrigation - "Mission Kakatiya" – Comprehensive restoration of Minor Irrigation Tanks – Administrative approval for Rs. 358.62 lakhs- Accorded – Orders – Issued.

=====

IRRIGATION & CAD (MI.T) DEPARTMENT

G.O.RT.No. 518

Dated:13 -07-2015.

Read:-

From the Chief Engineer, Minor Irrigation, (K) Hyderabad, Letter No. DCE-I/OT3-AEE/Mission Kakatiya/2015, Dt. 01.05.2015.

-o0o-

ORDER:-

Government of Telangana is launching restoration of all Minor Irrigation Tanks in the State of their original capacity and to effectively utilize the 265.00 TMC of water allocated for Minor Irrigation sector under Godavari & Krishna River Basins as a flagship programme under the name of "MISSION KAKATIYA".

2. In the reference read above, the Chief Engineer, Minor Irrigation (K), Hyderabad has submitted proposals under "Mission Kakatiya" for comprehensive Restoration of 28 tanks in Medak District for according administrative approval as per the statement shown below:-

SL.No	District	No. of tanks	Ayaut(Acres)	Cost Estimates of (in lakhs)
1	Medak	28	850.51	358.623.

3. Government after careful examination of the matter, hereby accord administrative approval for an amount of Rs. 3,58,62,000/- (Rupees three Crore fifty eight lakhs sixty two thousand only) towards the comprehensive of Restoration of 28 tanks in Medak District under "Mission Kakatiya" subject to ensuring the following and the statement showing the details of tanks proposed for restoration is annexed to this order. :-

- The provision made towards de-siltation in the estimates are based on the pre-levels and prudent assessments of quantities involved.
- The cost of repairs indicated are as per the actual requirement of the related components and quantities for restoration and the provisions made are in accordance to the Codal provisions and the guidelines issued in relation thereto.
- The due administrative and technical sanctions precede initiation of tender process.
- There are no overlaps of proposed works or part of works under other sanctioned schemes and /or duplication.
- As good working season / non crop season is over as of now, it is advised to take measures to ground the above sanctioned works in further suitable working seasons so that the progress for works will not be hampered and quality of works not affected.

4. The expenditure sanctioned in para (3) above shall be debited to the Head of Account "4702-101-GH(11)-SM (23)-530/531 O.E".

5. The Chief Engineer, Minor Irrigation (K) Hyderabad shall take necessary action accordingly and to complete the work within the stipulated period without fail and furnish utilization certificate to Government, for the amount sanctioned in Para (3) above.

6. This order issues with the concurrence of Finance (EBS.IX) Department vide their U.O.No.6849/222/A2/EBS.IX/2015, Dated:20-06-2015.

(BY ORDER AND IN THE NAME OF THE GOVERNOR OF TELANGANA)

S.K. JOSHI

PRINCIPAL SECRETARY TO GOVERNMENT

To

The Chief Engineer, Minor Irrigation (K), Hyderabad

Copy to:-

The Dist. Collector, Medak Dist.,

The Finance (EBS.IX) Department.

The Accountant General, T.S. Hyderabad.

The Director of Works & Accounts, M.J. Market Road, T.S., Hyderabad.

PS to Hon'ble Minister (I. M, M&G and L A)

PS to Principal Secretary to Government, I & CAD Department.

PA to Dy. Secretary to Government (T), I & CAD Department

The I & CAD (MI.G) Department.SF/SCs (C.No.4558/MI.T-A2/2015).

//forwarded by order //

SECTION OFFICER

ANNEXURE - I											
Statement showing the details of tanks proposed for restoration under Mission Kakathiya											
Sl. no	unique I.D	Name of the Tank	Village	Mandal	Constituency	Longitude	Latitude	Ayacut	Cost for Repairs component Rs in Lakhs	Cost of Silt Removal	Total cost of the estimate
1	2	3	4	5	6	7	8	9	10	11	12
1	04-042-20-005-02-302	Gandicheru	Theegulnarsapur	Jagdevpur	Gajwel	78 50 25	17 51 57	15.00	2.61	0.77	3.38
2	04-042-45-013-01-312	Peerla Kunta	Damarkunta	Mulugu	Gajwel	78 46 02	17 41 29	12.00	3.32	0.48	3.80
3	04-042-45-013-02-320	Kayyakatta	Kashireddypally	Mulugu	Gajwel	78 45 11	17 42 15	10.00	3.07	0.73	3.80
4	04-042-45-006-01-308	Patel Kunta	Tunkibolaram	Mulugu	Gajwel	78 35 50	17 43 12	17.00	7.19	3.10	10.29
5	04-042-45-021-01-401	Marrikunta (Marri pada)	Zapthisingayapally	Mulugu	Gajwel	78 37 12	17 41 34	15.00	11.13	0.96	12.09
6	04-042-45-020-01-303	Papa Kunta	Gangadharpally	Mulugu	Gajwel	78 37 45	17 40 30	12.00	3.69	2.14	5.83
7	04-042-19-005-01-307	THETTE KUNTA	ankireddypalle	Kondapaka	Gajwel	78 54 41	18 00 21	9.05	3.78	0.02	3.80
8	04-042-43-028-01-304	Rajakunta	Manoharabad	Toopran	Gajwel	78 27 46	17 45 28	16.00	3.03	0.55	3.58
9	04-042-43-028-01-302	Esannakunta	Manoharabad	Toopran	Gajwel	78 27 40	17 45 40	15.00	7.47	0.55	8.02
10	04-042-43-011-01-315	Danaiah kunta	Yawapur	Toopran	Gajwel	78 30 43	17 49 53	10.00	2.12	0.00	2.12

Sl. no	unique I.D	Name of the Tank	Village	Mandal	Constituency	Longitude	Latitude	Ayacut	Cost for Repairs component Rs in Lakhs	Cost of Silt Removal	Total cost of the estimate
1	2	3	4	5	6	7	8	9	10	11	12
11	04-042-43-017-01-305	Ayeelakunta / Ayilla kunta	Ravelly	Toopran	Gajwel	78 27 16	17 49 11	20.00	2.97	0.36	3.33
12	04-042-21-020-01-304	kothacheru / Kothakunta	gajwel	Gajwel	Gajwel	78 41 49	17 51 21	15.00	9.62	0.00	9.62
13	04-042-21-009-01-308	Barricheru (Bandaroni cheruvu)	Bejgam / Bejgaon	Gajwel	Gajwel	78 41 13	17 57 12	32.00	8.57	3.31	11.88
14	04-042-44-011-08-101	Bandamcheru	Chowdaripally	Wargal	Gajwel	78 38 01	17 46 42	118.00	10.83	20.17	31.00
15	04-042-44-005-01-303	Banda kunta	Jabbapur	Wargal	Gajwel	78 36 48	17 49 20	30.00	12.59	5.16	17.75
16	04-041-22-018-04-302	Avusuloni kunta	Gollapally	Doulthabad	Dubbaka	78 35 52	17 55 03	33.16	10.64	2.11	12.75
17	04-041-22-023-01-305	Errakunta	Waddepally	Doulthabad	Dubbaka	78 34 14	17 52 20	63.01	6.11	2.71	8.82
18	04-041-22-018-04-305	Kothacheru	Gollapally	Doulthabad	Dubbaka	78 35 59	17 55 33	67.36	28.74	4.70	33.44
19	04-041-22-011-01-303	Narsingaraocheru	Tirumalapur	Doulthabad	Dubbaka	78 34 43	17 56 28	46.00	20.98	4.14	25.12
20	04-041-22-009-01-301	Ooracheru	Godugupally	Doulthabad	Dubbaka	78 37 20	18 02 13	45.27	22.19	3.16	25.35

Sl. no	unique I.D	Name of the Tank	Village	Mandal	Constituency	Longitude	Latitude	Ayacut	Cost for Repairs component Rs in Lakhs	Cost of Silt Removal	Total cost of the estimate (Rs. in
1	2	3	4	5	6	7	8	9	10	11	12
21	04-041-14-001-02-303	Kurmollakunta / Kurmoni Kunta	Shilajinagar	Dubbaka	Dubbaka	78 37 49	18 15 08	38.00	8.29	0.83	9.12
22	04-041-14-002-01-402	Ellammakunta	Potharam	Dubbaka	Dubbaka	78 38 13	18 13 23	30.00	6.32	2.82	9.14
23	04-041-14-001-01-304	Banjarukunta/ Banjari Kunta	Gambhirpur	Dubbaka	Dubbaka	78 36 39	18 11 55	25.11	12.79	2.48	15.27
24	04-041-14-020-02-401	Kothakunta	Gosanpally	Dubbaka	Dubbaka	78 37 29	18 08 54	25.40	3.70	2.23	5.93
25	04-041-14-013-01-304	Pancheru/ Pani Chervu	Appanapally	Dubbaka	Dubbaka	78 44 42	18 08 45	62.15	8.75	39.68	48.43
26	04-041-46-008-01-301	Muchapati kunta	Chandapur	Thoguta	Dubbak	78 41 38	17 58 51	23.00	9.92	0.48	10.40
27	04-041-46-004-01-304	Peddannakunta	Lingampet	Thoguta	Dubbak	78 57 23	18 01 44	20.00	11.53	1.37	12.90
28	04-041-46-006-01-301	Adavilacha kunta	Lingapur	Thoguta	Dubbak	78 39 27	17 59 00	26.00	11.13	0.53	11.66
							TOTAL	850.51	253.08	105.54	358.62